

Oil & Hazardous Materials Report Form  
Spill Number: A/155/92

DP

Subject:

Name (Last, First MI): DRAGON PRODUCTS COMP  
Address: US RT 1 Town: THOMASTON  
State: ME Zip-code: 04861 Telephone: 2075945555

Spill Information:

Location (Town): THOMASTON Spill Type: A  
Amount spilled: 20.00 gals.Y cu. yds.N lbs.N bbls.N  
Type of spill: 29  
Date of Spill: 92/03/22 (yy/mm/dd) Time of Spill: \_\_\_\_\_ (Military)  
Date Reported: 92/03/22 (yy/mm/dd) Time Reported: \_\_\_\_\_ (Military)  
Cause: 06 Detection method: 2I  
Incident code: ACMP DEP response time involved: 3.0 (hours)  
Number of wells at risk: 0 Number of wells impacted: 0  
Investigators' names: 1. GLEN WALL *GW*  
2. \_\_\_\_\_  
3. \_\_\_\_\_

Person Reporting Incident:

Name (Last, First MI): DRAGON PRODUCTS/STEVE WALLACE  
Address: US RT 1 Town: THOMASTON  
State: ME Zip-code: 04861 Telephone: 2075945555

Oil & Hazardous Materials Report Form

Spill Number: A/155/92 (continued)

Clean-up Information:

Total product recovered: 20.99 gals.Y cu. yds.N lbs.N bbls.N  
Method: C Non-recyclable: \_\_\_\_\_ gals.N bbls.N  
Solids: combustible: \_\_\_\_\_ cu. yds.N tonsN  
non-combustible: \_\_\_\_\_ cu.yds.  
Recyclable material: \_\_\_\_\_ gals.N cu. yds.N lbs.N bbls.N  
Number of filters installed: 0 Number of aerators installed: 0  
Disposal information:

Other Actions:

Reimbursement: to SF (surface water): N (Y/N)  
to GF (ground water): N (Y/N)  
to HWF (haz waste): N (Y/N)  
Third party damage claim expected: N (Y/N)  
Enforcement Referral: N (Y/N)

A-155-92

In March of 1992 Steve Wallace, of Dragon Products Cement, reported a diesel fuel spill at their cement Kiln in Thomaston, Maine. The spill occurred when a hose, the diesel pump dispenser, ruptured. This caused the release of about twenty gallons of diesel. The diesel fuel spilled onto the ground and into a storm drain. This drain empties into a cattail swamp and then into a quarry pond.

Mr. Wallace showed me where his employees had placed sorbent boom into the swamp to collect and contain the spill. They had done a very good job and the oil was contained. Mr. Wallace then told me he would have the hose repaired and also continue to monitor the cattail swamp.

GWA15592.DOC