

OIL & HAZARDOUS MATERIALS REPORT FORM

Spill Number A1140 88

MM
A

SUBJECT

Name (Last, First, MI): Dragon Cement Co
Address: Rt 1 Town: Thomston State: Me
Zip: 04861 - Telephone Number: () - - (Optional)

SPILL INFORMATION

Location (Town): Thomston Spill type: A (Table A)
Amount spilled: 300.0 (gals, yds3, lbs, or bbls)
Type of spill: 02 (Table B)
Date of spill: 8/17/17 (Yr/Mo/Dy) Time of spill: 2:30 (Military)
Date reported: 8/18/18 (Yr/Mo/Dy) Time reported: 0800 (Military)
Cause: 06 (Table C) Detection method: 2I (Table D)
Incident code: A-10-P (Table E) DEP response time involved: 4.0 (Hours)
No. of wells at risk: 0 No. of wells impacted: 0
Investigators' names: 1. David Sait
2. _____
3. _____

PERSON REPORTING INCIDENT

Name (Last, First, MI): Steve Wallace Steve
Address: Dragon Cement Town: Thomston State: Me
Zip: 04861 - Telephone Number: () - - (Optional)

CLEAN-UP INFORMATION

Total product recovered: 250.0 (gals, yds3, lbs, or bbls)
Method: C-F (Table K) Non-recyclable: 250.0 (gals, or bbls)
Solids combustible: 0.1 (yds3 or tons)
Solids non-combustible: 5.0 (yds3)
Recyclable material: 0 (gals, yds3, lbs, or bbls)
Number of filters installed: 0 , Number of aerators installed: 0
Disposal Information: fed into kiln

OTHER ACTIONS

Reimbursement: to SF (surface water) N (Y or N)
to GF (ground water) N (Y or N)
to HWF (haz waste) N (Y or N)
Third party damage claim expected: N (Y or N)
Enforcement referral: N (Y or N)

NAME(S) OF CHEMICAL(S) INVOLVED :

BRIEF REMARKS : (For more detailed Recommendations and Narratives use a separated sheet of paper.)

OIL SPILL # A-140-88

On 4/18/88 Steve Wallace of the Dragon Cement Co. called to report a spill of # 2 fuel oil. Most of the oil was absorbed in cement on the building floor but some reached a storm drain. From there the oil reached a small stream in back of the plant. Dragon Cement personnel had placed sorbent material in the stream and nearly all the oil had been recovered. No further action is required.

On 4-18-88 Steve Wallace of the **ENTER**
Dragas Cement Co. ~~Co~~ called to
report a spill of #2 fuel oil. Most
of the oil was absorbed in cement
on the building floor but some reached a
storm drain. From there the oil reached
a small stream in back of the plant.

Dragas Cement personnel had placed
sorbent material in the stream and
nearly all the oil had been recovered.
No further ~~work~~ action is required.