

MAINE DEPARTMENT OF ENVIRONMENT PROTECTION
OIL & HAZARDOUS MATERIALS REPORT

Spill Number: A-290-2002

Report Status: Final Report

MCD Town: THOMASTON

Local Name: THOMSTON

Primary Responder: DANIEL E DAVIS

Primary Product: Diesel {29} - 53 gals. ESTIMATE

Subject/Owner: DRAGON PRODUCTS - -

I. EVENT

Spill Info

Type Oil Incident {O}
Source Equipment - Heavy Equipment {HQ}
Cause Overfill {09}

Spill Date/Time

05/05/2002 14:00

Reporter Type/Detection Method

Type Spiller {2}
Method Visual Product {L}

Reported Date/Time

05/07/2002 10:15

Subject/Owner (Potential Responsible Party)

Contact --DRAGON PRODUCTS
PO BOX 191
RT 1
THOMASTON ME 04861 USA
2075945555

Comment

Reporter

Contact ANN THAYER-ENVIRONMENTAL MANAGER-DRAGON PRODUCTS
PO BOX 191
RT 1
THOMASTON ME 04861 USA
2075945555

Comment

Primary Responder and Other Employees

DANIEL E DAVIS (Primary Responder)

No Further Response Action Expected

II. SITE

Location

Location Type Business - Industrial {ID}
Name DRAGON PRODUCTS
Street Address RT 1
MCD Town THOMASTON
Local Name THOMSTON
State/Province ME

Spill Point

UTM North
UTM East

Wells and Media Affected

Wells Affected 0 Wells Impacted / 0 Wells At Risk
Media Affected Land{L}

Tanks Involved

Underground Tank / Site # 5056

III. CLEANUP**Product Reported**

Diesel {29}

Cleanup DTREE**Products Found/Amount Spilled**

Diesel {29}/ - 53 gals. ESTIMATE (Primary Product)

Material Recovered

Other Material {OM} - 53 gals. ESTIMATE

Recovery/Treatment Method

Sorbents {C}

Disposal InformationDRAGON PRODUCTS,
THOMASTON**IV. NARRATIVE**

See attached report by Dragon Products. No site visit made.

V. ATTACHMENTS**Attachment Type**

Paper Attach

Description

spillers report

File Name



P.O. BOX 191, U.S. ROUTE 1, THOMASTON, MAINE 04861 • (207) 594-5555

A-290-02

MEMORANDUM

TO: DAN DAVIS, MEDEP
FROM: ANN W. THAYER
SUBJECT: DIESEL SPILL AT DRAGON'S THOMASTON FACILITY
DATE: 5/7/02
CC: MARK CURTIS, DRAGON PRODUCTS

Dan –

As we discussed by phone, attached is the spill report for the diesel spill that occurred over the weekend. The spill was due to a fueling incident. The fuel was restricted to a concrete pad and was quickly contained. As further follow-up, we will be reviewing the incident at this month's safety committee meeting and the topic of spill response will be the recommended subject of department safety meetings for the month.

If you have questions or need additional information, please contact me.



P.O. Box 191, U.S. Route 1 * Thomaston, Maine 04861 * 207-594-5555

SPILL REPORT
DRAGON PRODUCTS COMPANY

Facility Name: Dragon Products Company, Inc.
P.O. Box 191
Thomaston, ME 04861

Contact Name: Ann Thayer, Environmental Manager
(207) 594-5555

Report Filed By: Eric Greiner Date: 5/6/02

Product Spilled: Diesel Gallons: Approx. 53

Cause of Discharge/Spill: Unattended fuel pump discharged fuel on ground after loader operator started fueling his loader. See attached report from shift supervisor for more detail.

Remedial Action: Upon returning to pump and finding fuel being discharged on ground operator shut off pump and cleaned spill. Shift supervisor called me at home at approximately 1410 on Saturday 5/4/02. See attached report from shift supervisor for more detail.

AWT

Requested incident review at Safety Comm meeting. Will provide procedure reminders for monthly safety meetings.

Reported to/(MEDEP):

DAW DAVIS - MEDEP - 287-7800 5/7/02 ~ 1000 hrs
287-7939 fax

Attached:

- ☐ Facility Location Map
☐ MSDS

RETURN COMPLETED FORM TO ENVIRONMENTAL DEPARTMENT

Around 1:45 Tim Parker and I was walking out from the Hoch silos elevator when we noticed Joe Fontaine sweeping up speedy dry over by the fuel tank at the garage. We walked up to Joe and I ask him what had happened, he said while he was filling the loader with diesel fuel he left the nozzle running, and went to used the portable toilet, when he came out of the toilet, diesel fuel was running on the ground. The diesel fuel stayed on the concrete. Joe thinks the loader may have taking about 26 gallons of diesel fuel the pump that he was using read 79 gallons, 53 gallons of diesel was spilled. Joe cleaned the diesel fuel up with speedy dry and put the mess in coal storage area.

James E. Bubar J.E.B.

5-4-02