

MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION  
OIL & HAZARDOUS MATERIALS REPORT

**Spill Number:** A-30-2008

**Report Status:** Final Report

**MCD Town:** THOMASTON  
**Local Name:** THOMASTON  
**Primary Responder:** DANIEL E DAVIS  
**Primary Product:** #2 Fuel Oil {02} - 125 gals. ESTIMATE  
**Subject/Owner:** H O BOUCHARD - -

**I. EVENT**

**Spill Info**

Type Oil Incident {O}  
Source Land Transportation - Fuel Supply Tank (Saddle) {  
Cause Accident - Human Error {17}

**Spill Date/Time**

01/09/2008 05:00

**Reporter Type/Detection Method**

Type Other Involved Party {7}  
Method Visual Product {L}

**Reported Date/Time**

01/09/2008 06:00

**Subject/Spiller (Potential Responsible Party)**

Contact --H O BOUCHARD

ME USA  
207

Comment

**Reporter**

Contact MICHAEL MARTUNAS-ENVIRONMENTAL MANAGER-DRAGON CEMENT

THOMASTON ME USA  
207-593-0147

Comment

**Primary Responder and Other Employees**

DANIEL E DAVIS (Primary Responder)

**II. SITE**

**Location**

Location Type Business - Industrial {ID}  
Name DRAGON PRODUCTS  
Street Address RT 1  
MCD Town THOMASTON  
Local Name THOMASTON  
State/Province ME

**Spill Point**

UTM North  
UTM East

**Wells and Media Affected**

Wells Affected 0 Wells Impacted / 0 Wells At Risk  
Media Affected Land{L}  
Inland Surface Water{I}

**Tanks Involved**

Underground Tank(s) Involved-5056

**III. CLEANUP****Product Reported**

#2 Fuel Oil {02}

**Cleanup DTREE****Products Found/Amount Spilled**

#2 Fuel Oil {02}/ - 125 gals. ESTIMATE (Primary Product)

**Material Recovered**

Contaminated Soil {CS} - 10 cu. yds. ESTIMATE

**Recovery/Treatment Method**

Sorbents {C}

**Disposal Information**

Dragon disposed of sand

**IV. NARRATIVE**

Approximately forty gallons of #2 oil was reported spilled when an H.O. Bouchard delivery driver failed to properly attach a fill hose to the tank fitting and it "popped off." Dragon personnel estimated the spill at 100 - 150 gallons and brought in a truckload of sand to contain and collect the oil which flowed overland and entered a storm drain. The sand and sorbents were run through the Dragon cement kiln for disposal. The outfall of the catch basin drainage was lined with sorbent boom and monitored. No further action is expected.

**V. ATTACHMENTS****Attachment Type**

Paper Attach

**Description**

dragon spill report

**File Name**



P.O. Box 191, U.S. Route 1 \* Thomaston, Maine 04861 \* 207-594-5555

**SPILL REPORT**  
**DRAGON PRODUCTS COMPANY**

Facility Name: Dragon Products Company, Inc.  
P.O. Box 191  
Thomaston, ME 04861

Contact Name: Michael Martunas, Environmental Compliance Coordinator  
(207) 593-0147

Report Filed By: Michael Martunas Date/Time: 1/9/2008 @ 5:00 a.m

Product Spilled: #2 Fuel oil Gallons: 100-150

Type of Surface: Asphalt and soil Location: Between pier 1 & 2

Source/Cause of Discharge/Spill: Bouchard delivery driver made #2 fuel oil delivery unannounced, and began filling 15,000 gallon underground storage tank without being received by Dragon. At approximately 5:00 a.m. the driver notified Dragon Shift Supervisor, Tim Parker, that his hose had "popped off" and he had spilled 10 - 40 gallons. Tim contacted Dragon's Oil Spill Coordinator, Michael Martunas. Tim immediately contacted the quarry and had sand brought up to control the spill. The oil, which approximated 100-150 gallons, had entered a stormwater drain. The drain was covered with plastic and sand. Sand was used berm and absorb

Remedial Action: any visible oil. Speedy dry was also used to absorb any oil. All oil contaminated soil and speedy dry is swept up and brought to the quarry, where it is mixed into the raw feed stock and processed, as permitted by Dragon's Title V and Solid Waste licenses. The stormwater drain runs to a culvert that discharges on the property and flows to Quarry 5. Absorbent booms were placed at the culvert and the area in being monitored for any visible oil.

Reported to/(MEDEP): Yes, Called the DEP Spill Hotline (800-482-0777) @ 6:00 a.m.

Attached:  Facility Location Map  
 MSDS