

MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION
OIL & HAZARDOUS MATERIALS REPORT

Spill Number: A-338-2006

Report Status: Final Report

MCD Town: THOMASTON

Local Name: THOMASTON

Primary Responder: JON ANDREWS

Primary Product: Hydraulic Oil {86} - 0.75 gals. ESTIMATE

Subject/Owner: DRAGON PRODUCTS - -

I. EVENT

Spill Info

Type Oil Incident {O}
Source Equipment - Heavy Equipment {HQ}
Cause Mechanical Failure - Piping/Hose {06}

Spill Date/Time

06/19/2006 (Time Unknown)

Reporter Type/Detection Method

Type Subject/Spiller {2}
Method Visual Product {L}

Reported Date/Time

06/21/2006 16:25

Subject/Spiller (Potential Responsible Party)

Contact --DRAGON PRODUCTS
US ROUTE 1
THOMASTON ME 04861 USA
207-594-5555

Comment

Reporter

Contact ERIC TREINER--DRAGON PRODUCTS
US ROUTE 1
THOMASTON ME 04861 USA
207-593-0100

Comment

Primary Responder and Other Employees

JON ANDREWS (Primary Responder)

II. SITE

Location

Location Type Business - Industrial {ID}
Name CEMENT PLANT
Street Address ROUTE 1
MCD Town THOMASTON
Local Name THOMASTON
State/Province ME

Spill Point

UTM North
UTM East

Wells and Media Affected

Wells Affected 0 Wells Impacted / 0 Wells At Risk
Media Affected Land{L}

Tanks Involved

None

III. CLEANUP**Product Reported**

Hydraulic Oil {86}

Cleanup DTREE**Products Found/Amount Spilled**

Hydraulic Oil {86}/ - 0.75 gals. ESTIMATE (Primary Product)

Material Recovered

Contaminated Soil {CS} - 0.1 cu. yds. ESTIMATE

Recovery/Treatment Method

Excavation {G}

Disposal InformationThe contaminated soil was sent
to an on-site cement kiln.**IV. NARRATIVE**

DEP received a late report that this minor hydraulic oil spill occurred from a back-hoe at this facility. Contaminated soil had been excavated and sent to the cement kiln on-site. No DEP site visit was conducted as a result of this event.

V. ATTACHMENTS**Attachment Type****Description****File Name**