

MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION  
OIL & HAZARDOUS MATERIALS REPORT

**Spill Number:** A-805-2008

**Report Status:** Final Report

**MCD Town:** THOMASTON  
**Local Name:** THOMASTON  
**Primary Responder:** GLEN WALL  
**Primary Product:** Hydraulic Oil {86} - 30 gals. ESTIMATE  
**Subject/Owner:** DRAGON PRODUCTS - -

**I. EVENT**

**Spill Info**

Type Oil Incident {O}  
Source Equipment - Industrial Machinery {IM}  
Cause Mechanical Failure - Piping/Hose {06}

**Spill Date/Time**

05/19/2008 (Time Unknown)

**Reporter Type/Detection Method**

Type Subject/Spiller {2}  
Method Visual Product {L}

**Reported Date/Time**

05/19/2008 13:30

**Subject/Spiller (Potential Responsible Party)**

Contact --DRAGON PRODUCTS  
PO BOX 191  
ROUTE ONE  
THOMASTON ME 04861 USA  
207-594-5555

Comment

**Reporter**

Contact MICHAEL MARTUNAS-ENVIRONMENTAL COMPLIANCE-DRAGON PRODUCTS  
PO BOX 191  
ROUTE ONE  
THOMASTON ME 04861 USA  
207-593-0147

Comment

**Primary Responder and Other Employees**

GLEN WALL (Primary Responder)

**II. SITE**

**Location**

Location Type Business - Industrial {ID}  
Name DRAGON PRODUCTS  
Street Address ROUTE ONE  
MCD Town THOMASTON  
Local Name THOMASTON  
State/Province ME

**Spill Point**

UTM North  
UTM East

**Wells and Media Affected**

Wells Affected 0 Wells Impacted / 0 Wells At Risk  
Media Affected Land{L}

**Tanks Involved**

None

**III. CLEANUP****Product Reported**

Hydraulic Oil {86}

**Cleanup DTREE****Products Found/Amount Spilled**

Hydraulic Oil {86}/ - 30 gals. ESTIMATE (Primary Product)

**Material Recovered**

Other Material {OM} - 400 lbs. ESTIMATE

**Recovery/Treatment Method**

Sorbents {C}

**Disposal Information**speedi dri used by Dragon and  
disposed by Dragon.**IV. NARRATIVE**

On 5-19-2008 Michael Martunas reported a thirty gallon release of hydraulic oil. This spill occurred at the Dragon Products facility in Thomaston, Maine.

The spill occurred in the Rawmill Lube Room and the cause was a cracked fitting on a hydraulic hose. The oil spilled onto the concrete floor and a crew from Dragon cleaned up the material with speedi dri.

No site visit was made and no further action is expected.

**V. ATTACHMENTS****Attachment Type**

Paper Attach

**Description**

Spill report form from Dragon Products

**File Name**

A-805-2008



P.O. Box 191, U.S. Route 1 \* Thomaston, Maine 04861 \* 207-594-5555

**SPILL REPORT**  
**DRAGON PRODUCTS COMPANY**

Facility Name: Dragon Products Company, Inc.  
P.O. Box 191  
Thomaston, ME 04861

Contact Name: Michael Martunas, Environmental Compliance Coordinator  
(207) 593-0147

Report Filed By: Michael Martunas Date: 5-19-08

Product Spilled: T220 - Hydraulic Gallons: 30

Type of Surface: Concrete Location: Rawmill Lube Room

Cause of Discharge/Spill: Fitting on filter cart broke.  
Allowing oil to leak.

Remedial Action: Put down 10 bags of speedy  
dri and some oil absorbent pads.  
Shoveled up speedy-dri and bagged  
diapers.

Reported to/(MEDEP): Yes, Called the DEP Spill Hotline (800-482-0777) @ 130 pm

Attached:  Facility Location Map  
 MSDS