

MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION  
OIL & HAZARDOUS MATERIALS REPORT

**Spill Number: A-245-2008**

**Report Status:** Final Report

**MCD Town:** THOMASTON

**Local Name:** THOMASTON

**Primary Responder:** PETER J BLANCHARD

**Primary Product:** #2 Fuel Oil {02} - 20 gals. ESTIMATE

**Subject/Owner:** DRAGON PRODUCTS CO - -

**I. EVENT**

**Spill Info**

Type Oil Incident {O}  
Source Storage Unit - Aboveground Storage Tank {TA}  
Cause Mechanical Failure - Other {23}

**Spill Date/Time**

04/14/2008 07:00

**Reporter Type/Detection Method**

Type Subject/Spiller {2}  
Method Visual Product {L}

**Reported Date/Time**

04/14/2008 09:00

**Subject/Spiller (Potential Responsible Party)**

Contact --DRAGON PRODUCTS CO  
US ROUTE 1  
THOMASTON ME 04861 USA  
207 593-0147

Comment Mike Martunas, contact

**Reporter**

Contact MIKE MARTUNAS--DRAGON PRODUCTS CO  
US ROUTE 1  
THOMASTON ME 04861 USA  
207 593-0147

Comment

**Primary Responder and Other Employees**

PETER J BLANCHARD (Primary Responder)

**II. SITE**

**Location**

Location Type Business - Industrial {ID}  
Name DRAGON PRODUCTS CO  
Street Address US ROUTE 1  
MCD Town THOMASTON  
Local Name THOMASTON  
State/Province ME

**Spill Point**

UTM North  
UTM East

**Wells and Media Affected**

Wells Affected None Specified  
Media Affected Interior Surface {S}  
Land {L}

**Tanks Involved**

Above Ground Tank(s) Involved-Tank Inside

**III. CLEANUP****Product Reported**

#2 Fuel Oil {02}

**Cleanup DTREE****Products Found/Amount Spilled**

#2 Fuel Oil {02}/ - 20 gals. ESTIMATE (Primary Product)

**Material Recovered**

Other Material {OM} - 200 lbs. ESTIMATE

Contaminated Soil {CS} - UNKNOWN

**Recovery/Treatment Method**

Excavation {G}

Sorbents {C}

**Disposal Information**Disposal at Dragon Products'  
plant.**IV. NARRATIVE**

Mike Martunas contacted this office to report a fuel oil spill at Dragon Products Co. The spill occurred in the stockroom balcony when a float inside a 50 gallon day tank stuck and the tank overflowed to the concrete floor. The oil was discovered by a worker and the furnace that supplied the tank was shut off. Cleanup with speedi dri sorbent and hand shovelling. Materials were disposed of at the Dragon Product's plant in accordance with their Solid Waste License. No site visit was made.

**V. ATTACHMENTS****Attachment Type**

Paper Attach

**Description**

Dragon Products spill report

**File Name**



P.O. Box 191, U.S. Route 1 \* Thomaston, Maine 04861 \* 207-594-5555

**SPILL REPORT  
DRAGON PRODUCTS COMPANY**

Facility Name: Dragon Products Company LLC  
P.O. Box 191  
Thomaston, ME 04861

Contact Name: Michael Martunas, Environmental Manager  
(207) 593-0147

Report Filed By: Michael Martunas Date/Time: 4/14/08 @ 7:00 a.m.

Product Spilled: # 2 fuel oil Gallons: ~20 gallons

Type of Surface: Concrete Location Stockroom balcony

Source/Cause of Discharge/Spill: The float inside a 50 gal. storage tank stuck, causing oil to leak out of the vent.  
Float was inspected and cleaned and is working properly and is back in service.

Remedial Action: The furnace that supplies the tank was shut off. Speedy-dry was used to dike the area and contain the product. Speedy-dry and absorbent pads were used to absorb the oil. The oil soaked material was disposed of at the facility per Dragon's Solid Waste Order S-20851-WK-A-N.

Reported to/(MEDEP): Yes, Called the DEP Spill Hotline (800-482-0777) @ 9:00 on 4/14/08

Attached:  Facility Location Map  
 MSDS