## MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION OIL & HAZARDOUS MATERIALS REPORT

**Spill Number:** 

A-245-2008

**Report Status:** 

Final Report

MCD Town: THOMASTON

Local Name: THOMASTON

Primary Responder: PETER J BLANCHARD

Primary Product: #2 Fuel Oil {02} - 20 gals. ESTIMATE

Subject/Owner: DRAGON PRODUCTS CO - -

#### I. EVENT

Spill Info

Oil Incident {O}

Spill Date/Time

Type Source

Storage Unit - Aboveground Storage Tank {TA}

04/14/2008 07:00

Cause

Mechanical Failure - Other {23}

Reporter Type/Detection Method

Reported Date/Time

Type Method Subject/Spiller {2} Visual Product {L}

04/14/2008 09:00

## Subject/Spiller (Potential Responsible Party)

Contact

-- DRAGON PRODUCTS CO

US ROUTE 1

THOMASTON ME 04861 USA

207 593-0147

Comment

Mike Martunas, contact

Reporter

Contact

MIKE MARTUNAS--DRAGON PRODUCTS CO

US ROUTE 1

THOMASTON ME 04861 USA

207 593-0147

Comment

## Primary Responder and Other Employees

PETER J BLANCHARD (Primary Responder)

#### III: SITE

Location

Business - Industrial {ID}

Name

DRAGON PRODUCTS CO

Street Address

Location Type

US ROUTE 1

MCD Town

THOMASTON

Local Name State/Province **THOMASTON** ME

**Spill Point** 

**UTM North UTM East** 

#### Wells and Media Affected

Wells Affected

None Specified

Media Affected

Interior Surface (S)

Land{L}

Tanks Involved

Above Ground Tank(s) Involved-Tank Inside

Final Report A-245-2008 THOMASTON

III. CLEANUP and a construction of the property of the construction of the constructio

Product Reported

**Cleanup DTREE** 

#2 Fuel Oil {02}

Products Found/Amount Spilled

#2 Fuel Oil {02}/ - 20 gals. ESTIMATE (Primary Product)

**Material Recovered** 

Excavation {G}

Sorbents {C}

Other Material {OM} - 200 lbs. ESTIMATE

Contaminated Soil {CS} - UNKNOWN

Recovery/Treatment Method:

**Disposal Information** 

Disposal at Dragon Products'

plant.

IV. NARRATINE

Mike Martunas contacted this office to report a fuel oil spill at Dragon Products Co. The spill occurred in the stockroom balcony when a float inside a 50 gallon day tank stuck and the tank overflowed to the concrete floor. The oil was discovered by a worker and the furnace that supplied the tank was shut off. Cleanup with speedi dri sorbent and hand shovelling. Materials were disposed of at the Dragon Product's plant in accordance with their Solid Waste License. No site visit was made.

V. ATTACHMENTS

Paper Attach

Attachment Type Description

<u>Description</u>
Dragon Products spill report

Printed: 6/25/2010 11:12:22AM



P.O. Box 191, U.S. Route 1 \* Thomaston, Maine 04861 \* 207-594-5555

# SPILL REPORT DRAGON PRODUCTS COMPANY

Facility Name:	Dragon Products Con P.O. Box 191 Thomaston, ME 0486	h. 9 9
Contact Name:	Michael Martunas, En (207) 593-0147	vironmental Manager
Report Filed By:	Michael Martunas	Date/Time: 4/14/08 @ 7:00 a.m.
Product Spilled:	# 2 fuel oil	Gallons: ~20 gallons
Type of Surface:	Concrete	Location Stockroom balcony
Source/Cause of Discharge/Spill: Remedial Action:	The furnace that supplies the ta the area and contain the product absorb the oil. The oil soaked m	e tank stuck, causing oil to leak out of the vent.  I and is working properly and is back in service.  I and is working properly and is back in service.  In the service of the vent.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.  I and is working properly and is back in service.
	Solid Waste Order S-20851-WK	A-N.
Reported to/(MEDE)		ll Hotline (800-482-0777) @ 9:00 on 4/14/08
Attached:	Facility Location Map MSDS	