MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION OIL & HAZARDOUS MATERIALS REPORT

Spill Number: A-282-2007

Report Status: Final Report

MCD Town: THOMASTON Local Name: THOMASTON

Primary Responder: JON ANDREWS

Primary Product: Lube Oil {10} - 8 gals. ESTIMATE

Subject/Owner: DRAGON PRODUCTS COMPANY - -

Reported Date/Time

Spill Info Spill Date/Time

Type Oil Incident {O} 05/22/2007 13:30

Source Equipment - Industrial Machinery {IM}
Cause Mechanical Failure - Gasket/Seal {22}

Reporter Type/Detection Method

Type Subject/Spiller {2} 05/22/2007 14:00

Method Visual Product {L}

Subject/Spiller (Potential Responsible Party)

Contact -- DRAGON PRODUCTS COMPANY

P.O. BOX 191 US ROUTE 1

THOMASTON ME 04861 USA

207-594-5555

Comment

Reporter

Contact MICHAEL MARTUNAS--DRAGON PRODUCTS COMPANY

P.O. BOX 191 US ROUTE 1

THOMASTON ME 04861 USA

207-593-0147

Comment

Primary Responder and Other Employees

JON ANDREWS (Primary Responder)

HISTOCHUM TO THE PROPERTY OF T

Location
Location Type Business - Industrial {ID}

Spill Point
LITM North

ion Type Business - Industrial {ID} UTM North
Name DRAGON PRODUCTS COMPANY UTM East

Street Address U.S. RT 1

MCD Town THOMASTON

Local Name THOMASTON

State/Province ME

Wells and Media Affected Tanks Involved

Wells Affected 0 Wells Impacted / 0 Wells At Risk None

Media Affected Land {L}

Printed: 6/4/2010 3:25:57PM Page 1 of 2

Final Report A-282-2007 THOMASTON

III. CLEANUP

Product Reported

Cleanup DTREE

Lube Oil {10}

Products Found/Amount Spilled

Lube Oil {10}/ - 8 gals. ESTIMATE (Primary Product)

Material Recovered

Other Material {OM} - 80 lbs. ESTIMATE

Recovery/Treatment Method:

Disposal Information

Disposed by spiller (run through kiln).

Sorbents {C}

IV. NARRATIME THE PROPERTY OF THE PROPERTY OF

Department of Environmental Protection received a report that about 8-gallons of gear oil spilled at this facility when a seal failed. Oil spilled to a concrete catwalk and was collected using sorbents (speedee-dry) which was then run through the kiln. No site visit was made.

V. ATTACHMENTS

Attachment Type Description

<u>File Name</u>

Paper Attach

Printed: 6/4/2010 3:25:57PM Page 2 of 2



P.O. Box 191, U.S. Route 1 * Thomaston, Maine 04861 * 207-594-5555

SPILL REPORT DRAGON PRODUCTS COMPANY

Facility Name:	Dragon Products Company, Inc. P.O. Box 191 Thomaston, ME 04861	
Contact Name:	Michael Martunas, Environmental Compliance Coordinator (207) 593-0147	
Report Filed By:	Michael Martunas	Date: 5/22/2007
Product Spilled:	Gear Oil	Gallons: ~5-10
Type of Surface:	Concrete	Location Kiln catwalk, pier 3
Cause of Discharge/Spill:	Approximately 1:45 the spill was found on the kiln catwalk, pier 3.	
	Gear oil from the Jacking Engine Reducer on Pier #3 was leaking out of a ruptured seal.	
	· .	· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·	
Remedial Action:	Cleanup team mobilized immediately after spill was found. Absorbent material (Speedi Dry) and pads were used to clean up all free product. Material was collected for disposal at the Thomaston Cement plant facility.	
	Seal for the J.E.R. was replaced and the area cleaned.	
Reported to/(MEDEP):	Yes, Called the DEP Spill Hotline (800-482-0777) @ 2:00	
Attached:	Facility Location Map	
	MSDS	