




**GAC CHEMICAL CORPORATION
PERMIT BY RULE NOTIFICATION**

Photo No. 1	
Photo Date: July 30, 2024	
Site Location: Stockton Harbor	
Description: Dislodged riprap and exposed geotextile fabric at toe of slope	
Photo By: Eric Madachik	

Photo No. 2	
Photo Date: July 30, 2024	
Site Location: Stockton Harbor	
Description: Wide view of stabilization area	
Photo By: Eric Madachik	



**GAC CHEMICAL CORPORATION
PERMIT BY RULE NOTIFICATION**

Photo No. 3	
Photo Date: July 30, 2024	
Site Location: Stockton Harbor	
Description: Erosion and undercutting of soil	
Photo By: Eric Madachik	

Photo No. 4	
Photo Date: July 30, 2024	
Site Location: Stockton Harbor	
Description: Erosion, dislodged riprap, and geotextile viewed from top of slope	
Photo By: Eric Madachik	