

OIL & HAZARDOUS MATERIALS REPORT FORM

Spill Number A/451/88 PC

SUBJECT

Name (Last, First, MI): Dragon Products Co. Inc.
 Address: Rte 1, Box 191 Town: THOMASTON State: ME
 Zip: -04861 Telephone Number: (207) - 594 - 5335 (Optional)

SPILL INFORMATION KE

Location (Town): THOMASTON Spill type: E (Table A)
 Amount spilled: 30.99 (gals, yds³, lbs, or bbls)
 Type of spill: 02 (Table B)
 Date of spill: 88/10/25 (Yr/Mo/Dy) Time of spill: ? (Military)
 Date reported: 88/10/25 (Yr/Mo/Dy) Time reported: 1000 (Military)
 Cause: 18 (Table C) Detection method: 2J (Table D)
 Incident code: ACMSU (Table E) DEP response time involved: 4 (Hours)
 No. of wells at risk: 0 No. of wells impacted: 0
 Investigators' names: 1. AL Mc Neilly
 2. _____
 3. _____

PERSON REPORTING INCIDENT

Name (Last, First, MI): WALLACE Steve
 Address: Dragon Products, Rte 1 Town: THOMASTON State: Me
 Zip: -04861 Telephone Number: (207) - 594 - 5335 (Optional)

CLEAN-UP INFORMATION

Total product recovered: 25.99 (gals, yds³, lbs, or bbls)
 Method: G (Table K) Non-recyclable: 25.99 (gals, or bbls)
 Solids combustible: 0 (yds³, or tons)
 Solids non-combustible 20 yds³
 Recyclable material: 20 (gals, yds³, lbs, or bbls)
 Number of filters installed: 0 Number of aerators installed: 0
 Disposal Information: Soil mixed in with materials used
in cement making process

OTHER ACTIONS

Reimbursement: to SF (surface water) N (Y or N)
 to GF (ground water) N (Y or N)
 to HWF (haz waste) N (Y or N)
 Third party damage claim expected: N (Y or N)
 Enforcement referral: N (Y or N)

NAME(S) OF CHEMICAL(S) INVOLVED :

BRIEF REMARKS : (For more detailed Recommendations and Narratives use a separated sheet of paper.)

12,000 #2 Fuel oil tank at Dragon Products
 Abandoned in place. Tank was completely encased in
 cement which made removal extremely difficult. Clean
 Harbors cleaned out tank & it was filled with sand.

TANK ABANDONMENT INFORMATION

SPILL NUMBER A 1451/88

DATE OF INVESTIGATION 10/25/88

Facility name DRAGON PRODUCTS Co Inc
 Address Rte 1 Box 191 THOMASTON
 Phone Number 594-5555
 Contractor name FERIALOLO CONST.
 Address ROCKPORT Me.
 Phone number _____

KE

10 day notice provided _____ Less than 10 days provided
 _____ notice waived _____ No notice given

*** PLEASE CHECK APPROPRIATE FIELDS ***

Samples taken : SOIL _____ GROUNDWATER _____ TANK CONTENTS _____
 PHOTOGRAPHS TAKEN _____

Please number the tanks viewed _____

General Tank Information

UST Reg. #	<u>5056</u>	_____	_____	_____	_____
Size of Tank	<u>12,000</u>	_____	_____	_____	_____
Tank Construction (Tbl L)	<u>A</u>	_____	_____	_____	_____
Tank Age (Tbl M)	<u>7</u>	_____	_____	_____	_____
Piping Const. (Tbl L)	<u>0</u>	_____	_____	_____	_____
Status (Tbl P)	<u>A6</u>	_____	_____	_____	_____

Tank Condition

Holes observed	_____	_____	_____	_____	_____
More than 10 holes	_____	_____	_____	_____	_____
Tank not observed	<input checked="" type="checkbox"/>	_____	_____	_____	_____

Pipe Condition

Piping not to Regulation	_____	_____	_____	_____	_____
No leaks observed	_____	_____	_____	_____	_____
Broken fittings	_____	_____	_____	_____	_____
Leaking fittings	_____	_____	_____	_____	_____
Corrosion leaks	_____	_____	_____	_____	_____
Piping removed	_____	_____	_____	_____	_____
Piping not observed	<input checked="" type="checkbox"/>	_____	_____	_____	_____

Tank Installstion Condition

Tank on bedrock	_____	_____	_____	_____	_____
Tank within 3' of bedrock	_____	_____	_____	_____	_____
Water table seen in hole	<input checked="" type="checkbox"/>	_____	_____	_____	_____
Back filled with sand	_____	_____	_____	_____	_____
" " w/ crushed stone	_____	_____	_____	_____	_____
Non standard fill used	<input checked="" type="checkbox"/>	_____	_____	_____	_____

Soil Contamination

None observed	_____	_____	_____	_____	_____
Odor only observed	_____	_____	_____	_____	_____
Soil contaminated	<input checked="" type="checkbox"/>	_____	_____	_____	_____
Free product observed	_____	_____	_____	_____	_____

Distance to Drinking Water

Public supply within 1000'	_____	_____	_____	_____	_____
Nearest private supply within 300' not owned by the tank owner	_____	_____	_____	_____	_____

Tank Contents

Reg. gasoline	_____	_____	_____	_____	_____
Leaded gasoline	_____	_____	_____	_____	_____
#2 Fuel or Diesel	<input checked="" type="checkbox"/>	_____	_____	_____	_____
#6 oil	_____	_____	_____	_____	_____
Other	_____	_____	_____	_____	_____

OIL & HAZARDOUS MATERIALS REPORT FORM
Spill Number A-451-88

12,000 #2 fuel oil tank at Dragon Products abandoned in place. Tank was completely encased in cement which made removal extremely difficult. Clean Harbors cleaned out tank and it was filled with sand.

A-451-88

Abandonment of (an) Underground Tank(s) in Place

10/26/88

AL Mc NEILLY (signed) of the Department of Environmental Protection has determined that the following underground tank(s) at facility

facility name DRAGON PRODUCTS Co Inc phone # 594-5555
address Ate 1, Box 191 town THOMASTON
owner's name EL Cementos Del Norte phone # 594-5555
address Box 191 town THOMASTON
reg. # 5056

meets the following condition for abandonment in place - (abandonment in place is permitted by regulation) (check conditions applicable).

- a. Located beneath a building or other permanent structure which cannot be practically replaced;
b. Of a size and type of construction that it cannot be removed;
c. Inaccessible to heavy equipment necessary for removal; or
d. Positioned in such a manner that removal would endanger the structural integrity of nearby tanks.

Describe or diagram location of tank(s) meeting conditions (list tank number(s) as listed on registration certificate).

conditions above not demonstrated, Board of Environmental Protection variance required or tank must be removed (see notes).

DO NOT PROCEED WITH ABANDONMENT IN PLACE UNTIL AND UNLESS A BOARD VARIANCE IS GRANTED.

Describe or diagram location of tank(s) requiring a variance.

12,000 gal #2 Fuel Oil Tank was completely encased in concrete, including a cement pad. Filled in place with sand. ATIK being cleaned out by Clean Harbors