

MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION
OIL & HAZARDOUS MATERIALS REPORT

Spill Number: A-524-2003

Report Status: Final Report

MCD Town: THOMASTON

Local Name: THOMASTON

Primary Responder: PETER J BLANCHARD

Primary Product: Hydraulic Oil {86} - 22 gals. ESTIMATE

Subject/Owner: CIANBRO CORP - -

EVENT

Spill Info

Type Oil Incident {O}
Source Land Transportation - Truck {TR}
Cause Mechanical Failure - Piping/Hose {06}

Spill Date/Time

10/14/2003 15:30

Reporter Type/Detection Method

Type Subject/Spiller {2}
Method Visual Product {L}

Reported Date/Time

10/14/2003 16:06

Subject/Owner (Potential Responsible Party)

Contact --CIANBRO CORP
ONE HUNNEWELL SQ
PO BOX 1000
PITTSFIELD ME 04967 USA
207-487-3311

Comment Joe Plourde, contact

Reporter

Contact --CIANBRO CORP
ONE HUNNEWELL SQ
PO BOX 1000
PITTSFIELD ME 04967 USA
207-487-3311

Comment Joe Plourde, contact

Other Contact

Contact --DRAGON PRODUCTS
RT 1
THOMASTON ME 04861 USA
207-596-5880

Comment Cement plant, contact Kelly Gates

Primary Responder and Other Employees

PETER J BLANCHARD (Primary Responder)

No Further Response Action Expected

II. SITE

Location

Location Type Business - Industrial {ID}
Name DRAGON PRODUCTS
Street Address RT 1
MCD Town THOMASTON
Local Name THOMASTON
State/Province ME

Spill Point

UTM North
UTM East

Wells and Media Affected

Wells Affected 0 Wells Impacted / 0 Wells At Risk
Media Affected Land{L}

Tanks Involved

None

III. CLEANUP**Product Reported**

Hydraulic Oil {86}

Cleanup DTREE**Products Found/Amount Spilled**

Hydraulic Oil {86}/ - 22 gals. ESTIMATE (Primary Product)

Material Recovered

Contaminated Soil {CS} - 1.53 tons ACTUAL

Recovery/Treatment Method

Excavation {G}

Disposal InformationDisposal of contaminated soil
in Dragon cement kiln.**IV. NARRATIVE**

Joe Plourde of Cianbro called in a spill of hydraulic oil. Cianbro was contracted to do some upgrades at the Dragon Cement Kiln in Thomaston. During the course of operations a boom truck unloading materials burst a hydraulic hose spraying oil to the ground. It took 22 gallons to refill the tank, thus the estimated volume of the spill. The soil was quickly excavated and stockpiled on site. I sent a spill letter to Kelley Gates at Dragon and they arranged to dispose of the soil on site in the cement kiln. No site visit was required, and no further action is anticipated. If you have to have a spill, not a bad location eh?

V. ATTACHMENTS**Attachment Type****Description****File Name**

Paper Attach

Spill letter 10-20-03

Paper Attach

Cianbro incident report 12-16-03



December 16, 2003

Mr. Peter Blanchard
Bureau of Oil & Hazardous Materials
Division of Response Services
State House Station 17
Augusta, Maine 04333

RE: Oil Spill #A-524-2003

Dear Mr. Blanchard:

Please find attached the Cianbro Corporation's Oil Spill Report for the hydraulic oil spill that occurred at our Dragon Products job site in Thomaston, ME. I apologize for being late with this report, it ended up on the wrong desk.

If you have any questions concerning this report, please call me at (207) 679-2245.

Respectfully,

Cianbro Corporation

Scott A. Knowlen CSP, CHMM, CHST
Manager of Environmental Hazards

Enclosure

CIANBRO CORPORATION

Oil Spill Report

Spill Date: 10/14/03 Time 3:10 a.m. p.m. ✓

Spill Location: DRAGON PRODUCTS Street _____ Route No. US RTE 1
State ME Town THOMASTON County KNOX

Equipment Type, Make and Size L8000 FORD BOOM TRUCK S/N 932-060 Weather CLEAR
Oil type HYDRAULIC Amount Released 22 9L Basis for Estimate AMOUNT TO REFILL
Did Spill Enter Water? Yes ___ No ✓ Name of Water Body _____
Visual Observation of Water (oil sheen, cloudy, etc.) N/A
Duration of Discharge From: 15 MIN TRUCK To GROUND
Cause of Spill 1" HYDRAULIC OIL LINE SPLIT

Cleanup Measures/Description of Items Cleaned/Depth of Soil Removed
USED 15 BAGS SPEEDI-DRY USED MINI BACKHOLE
TO EXCAVATE SOIL AND PLACE IN SCARF PAN

Contractor used? Y(N) Name of Contractor Used _____
Cleanup Completion: Date 10/14/03 Time 4:30 PM Amount Recovered 22 9L

Cleanup Waste: Name of Disposal Contractor
15 bags/barrels (soil/speedi-dry) brush
bags/barrels rags/pads/booms/burnables
other

Name/Address Telephone of Property Owner Suffering Damages DRAGON PRODUCTS
US RTE 1, THOMASTON ME 04861
Safety Dept. Contact ARMOND PLOURDE Date 10/14/03 Time 3:30 PM
Comments: PETER BLANCHARD WILL GIVE ANN THAYER
A LETTER FROM DEP TO HAVE CLEAN UP BURNED
IN KILN

Measures Taken To Prevent Reoccurrence of This Type of Incident REPLACED HOSE ON
BOOM TRUCK

I hereby certify to the best of my knowledge that the information contained in this report and attachments is accurate and complete.

Signature of Supervisor [Signature] Date 10/14/03
Name of Supervisor (Print) Scott Clements

DEP Contact PETER BLANCHARD Date 10/14/03 Time 4:20 Spill No. A52403
NRC Contact _____ Date _____ Time _____ Spill No. _____
Contact Made to Agencies By JOE PLOURDE Date 10/14/03 Time 4:20 PM
Ambient Testing _____

Chemical Testing _____

KELLY GATES

Contaminated Soil Letter

Date 10-20-2003

DEP Spill # A-524-03

GENERATOR CIANBRO - DETROIT AVE PITTSFIELD

TRANSPORTER SAME ¹ JOE FLORDE
487 3311

REFERENCE: SHIPMENT OF OIL SPILL DEBRIS ON

10-14-03 PETER BLANCHARD OBSERVED THE
(date) (DEP representative)

clean up of oil spill debris at RUPTURED HYDRAULIC NOSE ON
(Description of incident)

HEAVY EQUIPMENT

This shipment consists of 2 yards ~~asphalt~~

drums of solid contaminated with HYDRAULIC OIL

Solid consist of (check as appropriate)

- sand, gravel or soil
- speedy-dri
- sorbent
- other

(describe or lists)

Facility is (check one)

- Landfill
- Land Spreading Site
- Asphalt Plant
- Asphalt Pug Mill
- other

DRAGON CEMENT

(describe)

Peter Blanchard
Signature - DEP Representative

Kelly Gates
Signature - Facility Representative

Attn: <u>PETER BLANCHARD</u>
State of Maine - DEP - Response Building
17 State House Station
Augusta, Maine 04333-0017

White - DEP Representative
Pink - Generator

Canary - Transporter
Goldenrod - Receiving facility

1.53 tons
Received