Oil & Hazardous Materials Report Form Spill Number: A/540/92 Subject: Name (Last, First MI): DRAGON PRODUCTS CO. Address: P.O. BOX 191 Town: THOMASTON
State: ME Zip-code: 04861 Telephone: 2075945555 Spill Information: Location (Town): THOMASTON Spill Type: A Amount spilled: 30.00 gals.Y cu. yds.N lbs.N bbls.N Type of spill: 80 Date of Spill: 92/10/29 (yy/mm/dd) Time of Spill: (Military)
Date Reported: 92/10/29 (yy/mm/dd) Time Reported: (Military) Cause: 11 Detection method: 2I Incident code: ETRL DEP response time involved: 0.5 (hours) Number of wells at risk: 0 Number of wells impacted: 0 Investigators' names: 1. ANDREWS, JON 2. 3. Person Reporting Incident: Name (Last, First MI): WALLACE, STEVE Address: Town:

State: Zip-code: Telephone: 2075945555

Oil & Hazardous Materials Report Form Spill Number: A/540/92 (continued) Clean-up Information: Total product recovered: 10.00 gals.N cu. yds.Y lbs.N bbls.N Method: G Non-recyclable: gals.N bbls.N

Solids: combustible: cu. yds.N tonsN
non-combustible: cu.yds.

Recyclable material: gals.N cu.yds.N lbs.N bbls.N

Number of filters installed: 0 Number of aerators installed: 0 Disposal information: SOIL TO CEMENT KILN

Other Actions:

Reimbursement: to SF (surface water): N (Y/N) to GF (ground water): N (Y/N) to HWF (haz waste): N (Y/N) Third party damage claim expected: N (Y/N) Enforcement Referral: N (Y/N)

A-540-92

Jon Andrews (DEP) received a report from Steve Wallace (Dragon Products) that an overturned truck at a quarry had resulted in spillage of hydraulic fluid (est. 20 gallons), diesel fuel (est. 10 gallons) and motor oil (trace).

Approximately 10 cubic yards of soil was excavated and taken to Dragon cement kiln for recycling.

No DEP personnel visited as a result of this incident.

3°	10/20/02
	Date $10/29/92$ DEP SPILL # $4-540-92$
	GENERATOR DRAGON FRODUCES CO
	TRANSPORTER DRAGON
	REFERENCE; SHIPMENT OF OIL SPILL DEBRIS WAS INFORMED OF
	ON U/29/92 ON HNDREWS -OBSERVED THE (date) (DEP representive)
	clean up of oil spill debris at the DRAGON QUARDY: THOMASTON (location)
	which resulted from Ushicle accident (description of incident)
	This shipment consists of
	hydraulic oil dissel motor oil (contaminant)
	Solids consist of (check as appropriate) Sand, gravel or soil speedy-dri sorbent other (descibe or lists)
	Facility is (check One) LandfillLand Spreading SiteAsphalt PlantAsphalt Pug MillotherCament wfg. plant
	Signature-DEP Representative Anda M. Lalady Signature-Facility Representative
Retun	White - DEP Representative Canary - Transporter Goldenrod - Receiving facility
	DEP, Oil AHN: JON AND 12003 Stn. 17 AUGUSTA 04333
	Stn. 17 Augusta 04333
	Hou of the contract of the con